Surface Water Results January 2020



City of Newcastle - Summerhill Waste Management Centre 141 Minmi Road, Wallsend, NSW

Environment Protection Licence 5897 - Condition M2

Monthly rainfall = 52.4mm

Durmaga	f Compling	No water discharged from site
Purpose of Sampling		No water discharged from site.
CN ID	EPL ID	
Parameter:		pH (pH unit)
SW55	55	N/A ¹
SW56	56	N/A ¹
SW57	57	N/A ¹
SW58a	61	N/A ¹
SW59	66	N/A ¹
Parameter:		Electrical Conductivity (µS/cm)
SW55	55	N/A ¹
SW56	56	N/A¹
SW57	57	N/A ¹
SW58a	61	N/A¹
SW59	66	N/A ¹
Parameter:		Suspended Solids (mg/L)
SW55	55	N/A ¹
SW56	56	N/A¹
SW57	57	N/A ¹
SW58a	61	N/A ¹
SW59	66	N/A ¹
Parameter:		Ammonia (mg/L)
SW55	55	N/A ¹
SW56	56	N/A ¹
SW57	57	N/A ¹
SW58a	61	N/A ¹
SW59	66	N/A¹
Parameter:		Biochemical Oxygen Demand (mg/L)
SW55	55	N/A ¹
SW56	56	N/A ¹
SW57	57	N/A ¹
SW58a	61	N/A ¹
SW59	66	N/A ¹

Surface Water Results January 2020



Summerhill Waste Management Centre

141 Minmi Road, Wallsend, NSW

Environment Protection Licence 5897 - Condition M2

Final data obtained: NA Date published:14/02/20

Notes:

CN = City of Newcastle
EPL = Environment Protection Licence
NR = no result (non-compliant sample, water body dry etc)
NA = Not applicable, sample not required
1. Water body not discharging from site

A copy of the Environmental Protection Licence can be viewed at:

http://app.epa.nsw.gov.au/prpoeoapp/

A map showing the location of monitoring points can be viewed at:

https://www.newcastle.nsw.gov.au/Living/Waste-and-recycling/Summerhill-Waste-management-Centre/Environmental-Monitoring

The City of Newcastle Page 2 of 2